Lead and Copper Sample Sites Certification (Form LCR1

PWS Name: Twinkle Brite

Address:

PMB 34 Box 10012.

Saipan, MP 96950

USA

PWS ID#:

System Classification:

Resident Population:

Non-Transient Population:

Sample Site Identification 1. The following sources have been explored to determine the piping materials of our entire distribution system (check all that apply) Utility distribution maps and records. XXUtility Operation and Maintenance (O&M) records. Utility design plans and specifications (proposed and/or as-buit records). XXXX Facility plumbing and/or building permits. Interviews with long-time employees or former employees. XXExcavation and/or direct inspection of plumbing pipes, fittings and fixtures. XXExisting water quality information. Interviews with local plumbing and/or heating/air conditioning contractors. Interviews with building inspectors and/or Department of Public Works. Interview with pipe suppliers, contractors and/or developers. Other sources of information 2. The following number of Lead & Copper sample sites were identified: Please attached the Number of Tier 1 sites: Lead & Copper Sample Number of Tier 2 sites: Sites Identification Table (Form LCR1) to (Community PWS only) Number of Tier 3 sites: this certification. Number of Other sites: Number of Alternative sites: (per regulations, based on resident & non-transient populations). 3. Minimum number of samples required: 5 235-0478 Angelito Galang Phone: 4. PWS Contact for Lead & Copper Sampling:

Sample Sites Certification

I certify that the information contained in this document and all attachments is true to the best of my knowledge and was gathered using the obove-mentioned resources. (Please Note: This certification must be signed by the Administrative Contact on record in DEQ's file or onother official of the water system. It cannot be signed by an independent contractor of the water system.)

Signature

Angelito Galang Print

Operation Manager

Title

9/7/2010

Date

Page 1 of 3