

# A Condition Scale Example for Hydrants:

1

No visible signs of rust or decay; No visible signs of damage; paint in good condition; all caps in place; all components operational; does not require maintenance interventions (only routine maintenance)

2

No visible signs of rust or decay; No visible signs of damage; paint in good condition; all caps in place; most or all components operational; requires minimal maintenance interventions to improve service

3

Some visible signs of rust or decay; Possible visible signs of damage; paint in decent condition; all caps in place; some components non-operational; requires maintenance interventions to improve operations

4

Visible signs of rust or decay; visible signs of damage; paint in poor condition; some caps may be missing; some components non-operational; requires significant maintenance or renewal

5

Visible signs of rust or decay; visible signs of damage; paint in poor condition; some caps may be missing; some components non-operational; requires replacement of some or all of the asset