Lead and Copper Sample Sites Certification (Form LCR1)

PWS Name: COMMONWEALTH UTILITIES CORP. (SAIPAN)

PWS ID#:MP0000001

Address:

P.O. Box 501220 CKRB

System Classification: Community

SAIPAN, MP 96950

Resident Population:

62,392

Non-Transient Population:

304

Sample	Sites	Iden	tification	
				8

1.	1. The following sources have been explored to determine the piping materials of our entire distribution system (check				
	all that apply): Utility distribution system maps and records				
	TX: 11 O 1 O 1 O 1 O 1 O 1 O 1 O 1 O 1 O 1	APPROVED 28/03			
	Utility design plans & specifications (proposed and/or as-built records)				
	Facility plumbing and/or building permits				
	Interviews with long-time employees or former employees, (Owner)				
	Excavation and/or direct inspection of plumbing pipes, fittings, and fixtures				
	Utility design plans & specifications (proposed and/or as-built records) Facility plumbing and/or building permits Interviews with long-time employees or former employees, (OUNER) Excavation and/or direct inspection of plumbing pipes, fittings, and fixtures Existing water quality information				
	Interviews with local plumbing and/or heating/air conditioning contractors				
	Interviews with building inspectors and/or Department of Public Works				
	Interviews with pipe suppliers, contractors and/or developers				
	Other sources of information				
2.					
	Number of Tier 1 sites:	Please attach the Lead & Copper			
	Number of Tier 2 sites:	Sample Sites			
	Number of Tier 3 sites: (Community PWS only)	Identification Table (Form LCR2) to			
	Number of Other sites: 60	this certification.			
	Number of Alternate sites:				
3. 4.		Phone: (670) 322-5740			
	Sample Sites Certification				
ga re	certify that the information contained in this document and all attachments is true to athered using the above-mentioned resources. (Please Note: This certification must ecord in DEQ's files or another official of the water system. It cannot be signed by system.)	an independent contractor of the water			
Signature					
	LORRAINE A. SABAUTA 62	8 03 Date			
C	Print CNMI Division of Environmental Quality	12/2002			
U.	ANIM DIVISION Of Environmental Enamy				